



Docket No.: 250599US40PCT

COMMISSIONER FOR PATENTS
ALEXANDRIA, VIRGINIA 22313



ATTORNEYS AT LAW

RICHARD D. KELLY
(703) 412-6241
RKELLY@OBLON.COM

RE: Application Serial No. 09/830,963
Applicants: Yogo KAWASAKI, et al.
Patent No. 6,930,258
Issued: August 16, 2005
For: MULTI-LAYER PRINTED CIRCUIT BOARD AND
METHOD OF MANUFACTURING MULTI-LAYER
PRINTED CIRCUIT BOARD

SIR:


Attached hereto for filing are the following papers:

Second Status Request for Certificate of Correction (in duplicate)

Our check in the amount of \$0 is attached covering any required fees. In the event any variance exists between the amount enclosed and the Patent Office charges for filing the above-noted documents, including any fees required under 37 C.F.R. 1.136 for any necessary Extension of Time to make the filing of the attached documents timely, please charge or credit the difference to our Deposit Account No. 15-0030. Further, if these papers are not considered timely filed, then a petition is hereby made under 37 C.F.R. 1.136 for the necessary extension of time. A duplicate copy of this sheet is enclosed.

Respectfully submitted,

OBLON, SPIVAK, McCLELLAND,
MAIER & NEUSTADT, P.C.
Norman F. Oblon


Richard D. Kelly

Registration No. 27,757
Raymond F. Cardillo, Jr.
Registration No. 40,440

James H. Knebel
Registration No. 22,630

Customer Number

22850

(703) 413-3000 (phone)
(703) 413-2220 (fax)

Certificate
OCT 05 2006
of Correction



Docket No.: 250599US40PCT

COMMISSIONER FOR PATENTS
ALEXANDRIA, VIRGINIA 22313



ATTORNEYS AT LAW

RICHARD D. KELLY
(703) 412-6241
RKELLY@OBLON.COM

RE: Application Serial No. 09/830,963
Applicants: Yogo KAWASAKI, et al.
Patent No. 6,930,258
Issued: August 16, 2005
For: MULTI-LAYER PRINTED CIRCUIT BOARD AND
METHOD OF MANUFACTURING MULTI-LAYER
PRINTED CIRCUIT BOARD

SIR:

Attached hereto for filing are the following papers:

Second Status Request for Certificate of Correction (in duplicate)

Our check in the amount of \$0 is attached covering any required fees. In the event any variance exists between the amount enclosed and the Patent Office charges for filing the above-noted documents, including any fees required under 37 C.F.R. 1.136 for any necessary Extension of Time to make the filing of the attached documents timely, please charge or credit the difference to our Deposit Account No. 15-0030. Further, if these papers are not considered timely filed, then a petition is hereby made under 37 C.F.R. 1.136 for the necessary extension of time. A duplicate copy of this sheet is enclosed.

Respectfully submitted,

OBLON, SPIVAK, McCLELLAND,
MAIER & NEUSTADT, P.C.
Norman F. Oblon



Richard D. Kelly

Registration No. 27,757
Raymond F. Cardillo, Jr.
Registration No. 40,440

James H. Knebel
Registration No. 22,630

Customer Number
22850

(703) 413-3000 (phone)
(703) 413-2220 (fax)



DOCKET NO.: 250599US40PCT/alh

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

IN RE APPLICATION OF:

Yogo KAWASAKI, et al.

PATENT NO: 6,930,258

CERTIFICATE OF CORRECTION

ISSUED: August 16, 2005

FOR: MULTI-LAYER PRINTED CIRCUIT BOARD AND METHOD OF
MANUFACTURING MULTI-LAYER PRINTED CIRCUIT BOARD

SECOND REQUEST

CERTIFICATE OF CORRECTION FOR STATUS REQUEST

Commissioner for Patents
Alexandria, VA 22313-1450

Sir:

The Patent Office is respectfully requested to provide a Certificate of Correction for this Application. A Request for Certificate of Correction and a Certificate of Correction Form PTO-1050 were filed September 7, 2005.

A duplicate of this letter is enclosed for your convenience.

Respectfully Submitted,

OBLON, SPIVAK, McCLELLAND,
MAIER & NEUSTADT, P.C.

Richard D. Kelly

Registration No. 27,757

Raymond F. Cardillo, Jr.

Registration No. 40,440

James H. Knebel

Registration No. 22,630

Customer Number

22850

Tel. (703) 413-3000
Fax. (703) 413-2220
(OSMMN 10/04)


DOCKET NO.: 250599US40PCT/alh

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

IN RE APPLICATION OF:

Yogo KAWASAKI, et al.

PATENT NO: 6,930,258



CERTIFICATE OF CORRECTION

ISSUED: August 16, 2005

FOR: MULTI-LAYER PRINTED CIRCUIT BOARD AND METHOD OF
MANUFACTURING MULTI-LAYER PRINTED CIRCUIT BOARD

SECOND REQUEST

CERTIFICATE OF CORRECTION FOR STATUS REQUEST

Commissioner for Patents
Alexandria, VA 22313-1450

Sir:

The Patent Office is respectfully requested to provide a Certificate of Correction for this Application. A Request for Certificate of Correction and a Certificate of Correction Form PTO-1050 were filed September 7, 2005.

A duplicate of this letter is enclosed for your convenience.

Respectfully Submitted,

OBLON, SPIVAK, McCLELLAND,
MAIER & NEUSTADT, P.C.

A handwritten signature in black ink, appearing to read "Richard D. Kelly". The signature is written over a horizontal line.

Richard D. Kelly

Registration No. 27,757
Raymond F. Cardillo, Jr.
Registration No. 40,440
James H. Knebel
Registration No. 22,630

Customer Number

22850

Tel. (703) 413-3000
Fax. (703) 413-2220
(OSMMN 10/04)